

SAPC-19415 ✓
Copy 2 of 4

MEMORANDUM FOR: Deputy Project Director

11 October 1957

SUBJECT : Engine Problems

REFERENCE : SAPC-20092

I agree with you that we should sometime this winter do a few tests along the lines suggested in paragraph 6 of reference to determine whether by leaving the ignition on during descent a quick and automatic relight would be ensured in the event of a flameout.

RMB
RICHARD M. BISSELL, JR.
Project Director

RMB:djm
1-Addressee
2-Pro. Dir. Chrono
3-Pro. Dir FU
4-Pro. Chrono

RECORDED